Navajo Abandoned Uranium Mine Site Screen Report

This form is for use at the site of abandoned uranium mines (AUM) located on Navajo Nation lands. Applicable sites include all mine and mine features that have or have not undergone reclamation by the Navajo Abandoned Mine Lands Reclamation Program, including features, adits and pits. Applicable sites also include all AUM sites listed in the USEPA CERCLIS database, all sites listed in the 2008 AUM GIS Report issued by USACOE and USEPA, all AUM sites on allotment lands associated with the Navajo Nation, and any and all AUM sites lands not listed in any database located on Navajo lands. Reconnaissance of any sites located on lands adjacent to Navajo lands but that are or may be impacting Navajo lands will need to be coordinated with the authorities appropriate to those lands.

The purpose of the form is to ascertain the status and location of the identified AUM site, to record all immediate site information associated with the mine site and to document the recommendation and/or decision on what additional steps, if any, are needed at the site.

Section 5 AUM Site

Navajo AUM Eastern Region

Prepared by:

Weston Solutions, Inc.

Contract: W91238-06-F-0083

12767.063.496.1111

May 2009

Part I **Site Identification, Location and Status** Site Names and ID numbers as applicable Mine ID: 346 Map ID: E72 **CERCLIS:** NNN 000 908 741 **NAMLRP:** NOT ASSIGNED **New Mexico Mining and Mineral Division ID:** NM0165 New Mexico Bureau of Geology and Mineral Resources: NMMK0168 Local name / Aliases: Westvaco, Febo, Los Tres Mosqueteros Chapter and local area: Baca/Haystack Chapter **Lat/Long:** 35.3849835153 N / -107.922234355 W Nearby road and highway: Blackwood road, Indian Route 41 Local Post Office: Prewitt, NM Land Status: check one or more and provide ownership and contact information below **Tribal Trust Land Tribal Fee Land** Allotment Fee land **Public lands Private Bureau of Land Mgmt**

Ownership and contact information:

State

The mine site property is classified as private land, but no residences were found within 0.25 miles of the site. New Mexico Mining and Minerals Division identifies the surface owner as the Cerillos Land Company, and mineral rights owner as the Newmont Mining Company.

Part II Site Observations

Observed Structures: list number of and describe human habitation status of structures at the following distances from mine:

0 to 200 feet: None **200 feet to 0.25 mile:** None

Observed Public or commercial structure: list and describe all schools, clinics, Chapter Houses, places of business and any other structure used by members of the community at the following distances:

0 to 200 feet: None **200 feet to 0.25 mile:** None

Levels measured around the perimeter(s) of the identified structure(s):

None

Observed water sources: list the number and type of wells and surface water sources that are potentially used for human consumption at the following distances from the mine:

0 to 0.25 miles: None 0.25 miles to 4 miles: None

Observed Sensitive environments: note and describe all sensitive environments located within visible range of the mine site, including: wetlands, endangered species habitats and approximate locations of sites that may be under protection of the government of the Navajo Nation.

None observed

Known Site History: include information from interviews with Chapter officials and residents.

Note information on mine ownership, period of operation, and type of mining operation.

The Section 5 mine consists of an area of 11,679.99 square meters. Any historical information pertaining to mining operations and historical ownership of the mine site appeared to be unclear. The New Mexico Mining and Minerals Division identified the operator in 1958 as Westvaco/Farris Mines.

Part III Type, number and reclamation status of mine features

Provide description and reclamation status of all mine sites and features at site. Include all waste piles, adits, pits and other features, and indicate whether they are open, closed, covered, capped, buried or unreclaimed. Indicate approximate size, shape and extent, including description of any reclamation caps. Note condition of all reclamation caps.

Reclamation status of the mine sites are currently unknown. No visible signs of reclamation were observed. One adit was observed at the site along the bluff with waste rock deposited down slope. Some waste piles were observed above the bluff on top of the mesa. No other mine features were observed during the site visit.

Part IV Summary of radiological readings

Background Locations

#1 22,797 cpm #2 9,592 cpm

Mine site: Section 5

- See Figures 1 and 2

Nearby Structure Perimeter - None

Describe any other radiological measurements:

A total of 1,367 gamma radiation measurements were collected from mine sites, ranging from 6,137 cpm to 319,350 cpm. The measurements are represented in Figures 1 and 2. Gamma radiation measurements collected at the adit were greater then 100,000 cpm . The New Mexico Mining and Minerals Division identified radiological measurements with background levels 50 counts per second (cps); adit 800 cps.

Part V Site sketch of all mine features and readings, including locations of all structures, sources of drinking water and any other important features and radiological readings.

Presented in Figures 1 and 2

Part VI Response Action Summary

Site Name(s): Section 5 Chapter: Baca/Haystack

Decision Criteria

Is there an unreclaimed waste pile at the site? Yes

At what distance from the waste pile is the nearest residential structure located? 0.5 mile

At what distances from the waste pile are there potential drinking water sources? 1.7 miles

Is there a reclamation cap or sealed adit in place at the site? No

Is the cap/seal functionally intact? N/A

Is the cap/seal sufficiently degraded to create a concern about releases? N/A

At what distance from the cap/seal is the nearest domestic structure located? N/A

At what distance from the cap/seal is the nearest domestic drinking water source? N/A

Summary of emergency response factors

None

Summary hazard ranking system factors

None

Summary of reclamation factors

No known reclamation

Part VII Photos



Photo 1. Section 5 Mine site, towards the south. Mine is in bluff adjacent to bench



Photo 2. Section 5 Mine site, adit in bluff



Photo 3. Section 5 Mine site, interior of adit



Photo 4. Section 5 Mine site, view to the west

Part VIII Contacts Reports and Information

Name Stanley Edison
Title or official role (if any) Navajo EPA Superfund Program
Address PO Box 2946, Window Rock, AZ 86515
Telephone number 928-871-6861
Information provided <u>General Background and Contact/Access Information</u>
Name Susan A. Lucas Kamat
Title or official role (if any) <u>AUM Data Manager – New Mexico Mining & Mineral Division</u>
Telephone number (505) 476-3408 fx: (505) 476-3408
Information provided <u>Background information and findings from 2008 New Mexico MMD</u>
Survey of mining sites.
Name
Title or official role (if any)
Telephone number
Information provided
Name
Title or official role (if any)
Telephone number
Information provided



